

Yara Pilbara Nitrates Pty Ltd Air Quality Monitoring Report February 2022

14/03/2022 650-200-REP-YPN-0053 Rev 0

Ambient Air Concentration of Gases NH₃, NO₂ and SO₂

Site	Date On	Date Off	NH ₃	NO ₂	SO ₂
			μg/m³	μg/m³	μg/m³
Site 5 - Burrup Road	No new results received to date				
Site 6 - Water Tanks					
Site 7 – Hearsons Cove					

Notes:

(1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd Air Quality Monitoring Report February 2022

14/03/2022

650-200-REP-YPN-0053

Rev 0

Airborne Particulate Concentration Total Suspended Particulates (TSP)

Period Start Date ^{(1),(2)}	Site 5 (Burrup Road) TSP	Site 6 (Water Tanks) TSP	Site 7 (Hearsons Cove) TSP
	μg/m³	μg/m³	μg/m³
05/01/2022	76	89	89
11/01/2022	36	36	41
17/01/2022	44	54	54
23/01/2022	39	45	48

Notes:

- (1) The date is the date that sampling commenced.
- (2) The Low Volume Air Sampler unit runs for a nominal 24 hours.
- (3) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd Air Quality Monitoring Report February 2022

14/03/2022 650-200-REP-YPN-0053 Rev 0

Deposited Dust - Total Dust Deposition per Month Insoluble and Soluble Fraction

Site 5 - Burrup Road		Date Deployed			
		Date Collected			
Parameter	Unit	Limit of Reporting			
Soluble solids	g/m²/month	0.7	No now results received to date		
Insoluble solids	g/m²/month	0.8	No new results received to date		

Site 6 - Water Tanks		Date Deployed		
		Date Collected		
Parameter	Unit	Limit of Reporting		
Soluble solids	g/m²/month	0.7	No new results received to date	
Insoluble solids	g/m²/month	0.8		

Site 7 – Hearsons Cove		Date Deployed		
		Date Collected		
Parameter	Unit	Limit of Reporting		
Soluble solids	g/m²/month	0.7	No new results received to date	
Insoluble solids	g/m²/month	0.8		

Notes:

(1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.