

Yara Pilbara Nitrates Pty Ltd Air Quality Monitoring Report August 2022

19/09/2022 650-200-REP-YPN-0059 Rev 0

Ambient Air Concentration of Gases NH₃, NO₂ and SO₂

Site	Date On	Date Off	NH₃ μg/m³	NO ₂ μg/m³	SO₂ µg/m³
Site 5 - Burrup Road	F3 F3				N. 3
Site 6 - Water Tanks	No new results received to date				
Site 7 – Hearson Cove					

Notes:

(1) Site 7 renamed from Deep Gorge to Hearson Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd Air Quality Monitoring Report August 2022

19/09/2022 650-200-REP-YPN-0059 Rev 0

Airborne Particulate Concentration Total Suspended Particulates (TSP)

Period Start Date ^{(1),(2)}	Site 5 (Burrup Road) TSP	Site 6 (Water Tanks) TSP	Site 7 (Hearsons Cove) TSP
	μg/m³	μg/m³	μg/m³
04-Jul-22	22	28	23
10-Jul-22	15	10	10
16-Jul-22	13	11	11
22-Jul-22	13	17	15
28-Jul-22	20	19	18
03-Aug-22	13	12	13

Notes:

- (1) The date is the date that sampling commenced.
- (2) The Low Volume Air Sampler unit runs for a nominal 24 hours.
- (3) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd Air Quality Monitoring Report August 2022

19/09/2022 650-200-REP-YPN-0059 Rev 0

Deposited Dust - Total Dust Deposition per Month Insoluble and Soluble Fraction

Sito E Purrun Bood		Date Deployed	1/06/2022	
Site 5 - Burrup Road	4	Date Collected	1/07/2022	
Parameter	Unit	Limit of Reporting		
Soluble solids	g/m²/month	0.7	1.1	
Insoluble solids	g/m²/month	0.8	1.1	

Site C. Wester Tenks		Date Deployed	1/06/2022	
Site 6 - Water Tanks		Date Collected	1/07/2022	
Parameter	Unit	Limit of Reporting		
Soluble solids	g/m²/month	0.7	1	
Insoluble solids	g/m²/month	0.8	<0.8	

Site 7 – Hearsons Cove		Date Deployed	1/06/2022	
Site 7 – nearsons C	ove	Date Collected	1/07/2022	
Parameter	Unit	Limit of Reporting		
Soluble solids	g/m²/month	0.7	1.3	
Insoluble solids	g/m²/month	0.8	<0.8	

Notes:

(1) Site 7 renamed from Deep Gorge to Hearson Cove due to site relocation in April 2020.