

Yara Pilbara Nitrates Pty Ltd Air Quality Monitoring Report November 2023

22/12/2023 650-200-REP-YPN-0074 Rev 0

Ambient Air Concentration of Gases NH₃, NO₂ and SO₂

Site	Date On	Date Off	NH₃ µg/m³	NO ₂	SO₂ µg/m³
Site 5 - Burrup Road					
Site 6 - Water Tanks	No new results received to date				
Site 7 – Hearsons Cove					

Notes:

(1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd Air Quality Monitoring Report November 2023

22/12/2023 650-200-REP-YPN-0074 Rev 0

Airborne Particulate Concentration Total Suspended Particulates (TSP)

Period Start Date ^{(1),(2)}	Site 5 (Burrup Road) TSP	Site 6 (Water Tanks) TSP	Site 7 (Hearsons Cove) TSP
	μg/m³	μg/m³	μg/m³
28-Aug-23	30	22	16
03-Sep-23	21	21	19
09-Sep-23	28	22	14
15-Sep-23	45	34	32
21-Sep-23	21	38	35
27-Sep-23	21	22	18

Notes:

- (1) The date is the date that sampling commenced.
- (2) The Low Volume Air Sampler unit runs for a nominal 24 hours.
- (3) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.



Yara Pilbara Nitrates Pty Ltd Air Quality Monitoring Report November 2023

22/12/2023 650-200-REP-YPN-0074 Rev 0

Deposited Dust - Total Dust Deposition per Month Insoluble and Soluble Fraction

Cita E. Durmur Band		Date Deployed	1/08/2023
Site 5 - Burrup Road	u	Date Collected	31/08/2023
Parameter	Unit	Limit of reporting	
Soluble solids	g/m²/month	0.7	<0.7
Insoluble solids	g/m²/month	0.8	0.8

Site 6 - Water Tanks		Date Deployed	1/08/2023
Site 6 - Water Tariks		Date Collected	31/08/2023
Parameter	Unit	Limit of reporting	
Soluble solids	g/m²/month	0.7	<0.7
Insoluble solids	g/m²/month	0.8	1.1

Site 7 – Hearsons Cove		Date Deployed	1/08/2023
Site 7 – Hearsons C	ove	Date Collected	31/08/2023
Parameter	Unit	Limit of reporting	
Soluble solids	g/m²/month	0.7	<0.7
Insoluble solids	g/m²/month	0.8	1.1

Notes:

(1) Site 7 renamed from Deep Gorge to Hearsons Cove due to site relocation in April 2020.